

FIG 1A




FIG 1B




FIG 2




FIG 3A

Noisy-Filtered image




FIG 3B




FIG 4A

File Defect/CRY15.AIM,  
Pitch 1.259 $\mu$ m, Angle 89.93 deg




FIG 4B

File Defect/CRY15.AIM,  
Pitch 1.259 $\mu$ m, Angle 89.93 deg




FIG 5A

File Defect/CRY515.AIM,  
Pitch 1.259 $\mu$ m, Angle 89.93 deg




FIG 5B

File Defect/CRY515.AIM,  
Pitch 1.259 $\mu$ m, Angle 89.93 deg




FIG 6A




FIG 6B

